

**RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA**

PROPERTY PARCEL NO.	JOB ADDRESS						INSPECTION AREA	<b>FINAL INSPECTIONS</b>	
	3917 Rio Linda Blvd.						6		
LEGAL DESCRIPTION						OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE
TITLE AND NAME			1/C	ADDRESS			ZIP	CITY LIC. NO.	TEL. NO.
GEN. CONTR.									
ELEC. CONTR.									
PLBG. CONTR.									
MECH. CONTR.									
ARCH. ENGR.									
OWNER									
CONST. LOAN LENDER									
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
							CENSUS TRCT. NO.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

**NATURE OF WORK:-**

PERMIT NO. S.P. -	<b>MICROFILM RECORD</b>			
ISSUED BY				
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
VALUATION \$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.U.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$	REMARKS AND/OR VARIANCES			
\$				
\$				
TOTAL FEES \$				

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
D-5358 W-6931 21-0931	R450F312 R449H499 R454R266				

MICROFILM RECORD

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
7/13/76	P. \$ 100	D-5358 \$ 7.50	Sewer Disc. & abandon well - DWLg	Mary Hall 6524 18th Street Same	Mary Hall 6524 18th Street Same	Mylon 7/15/76	
7/16/76	Wreck	W-6931 \$20	Wreck	Mary Hall 6524 18th Street R.T. Same	Mary Hall 6524 18th Street R.T. Same	Mylon 8-27-76	

RECORD OF SUBSEQUENT PERMITS ISSUED