

| | | | | | | | |
|------------------------------------|------|---|--------------------|---|------------------------------------|-----------|------------------|
| FINAL INSPECTIONS | | CITY OF SACRAMENTO BUILDING INSPECTIONS DIVISION | | | JOB ADDRESS 1630 Pebblewood Dr. | | AREA 6C |
| BUILDING BY | DATE | ASSESSOR PARCEL NUMBER | | LEGAL DESCRIPTION Lot 771 Woodbridge Unit No.7 | | | |
| ELECTRICAL BY | DATE | NAME OF FIRM | | ADDRESS | ZIP CODE | ACCT. NO. | PHONE NO. |
| PLUMBING BY | DATE | CONTRACTOR | | Morrison Homes Corp. | 3001 Truxel Rd. | 95833 | 1578000 927-4503 |
| MECHANICAL BY | DATE | OWNER | | Same | 4441 Auburn Blvd. #P | 95841 | Same 485 2931 |
| CERTIFICATE OF OCCUPANCY ISSUED BY | | DATE | ARCH. ENGR. | 1531 Chapala St. Santa Barbara, Ca. | | 93101 | C7733 963-8901 |
| MICROFILM RECORD | | | CONST. LOAN LENDER | | | | |

| | | | | | | | | | | | |
|-----------------------|------------|----|-------------|---|---------------|----------------|------------|-------------|------------|----------|------------------------------|
| PLANS AND APPLICATION | | | R684F286 | NO. OF STORIES | ROOF COVERING | AREA 1ST FLOOR | TOTAL AREA | GARAGE AREA | PATIO AREA | USE ZONE | BUILDING ELECT. MECH. PLUMB. |
| REEL NO. | FRAME NO:- | TO | | 1 | comp | | 1802 | 447 | porch 48 | | |
| REEL NO. | FRAME NO:- | TO | 1039 TO 478 | THIS PERMIT IS FOR: <input checked="" type="checkbox"/> BUILDING <input checked="" type="checkbox"/> MECHANICAL <input checked="" type="checkbox"/> PLUMBING <input checked="" type="checkbox"/> ELECTRICAL | | | | | | | |
| REEL NO. | FRAME NO:- | TO | | NATURE OF WORK IN DETAIL | | | | | | | |
| REEL NO. | FRAME NO:- | TO | | Construct new dwelling 3 bdrm with garage. | | | | | | | |
| REEL NO. | FRAME NO:- | TO | | MP 175 MPR 680F604-618 | | | | | | | |
| REEL NO. | FRAME NO:- | TO | | Street Width 64' | | | | | | | |

| | | | | | |
|--------------------------|--|------------------------|-----------|------------------------|-----------------------|
| REMARKS AND/OR VARIANCES | | VALUATION \$ | 35,040.00 | PERMIT-FEE | I |
| | | ISSUED BY: | Ritchie | | |
| | | DATE ISSUED | 8-14-81 | BUILDING PERMIT FEE \$ | 3 |
| | | | | | |
| | | BUILDING PERMIT FEE \$ | | PLAN CHECK FEE \$ | 8 |
| | | RDF FEE \$ | 385.00 | | |
| | | S.M.I. FEE \$ | 2.45 | REG. SEWER FEE \$ | OCCUP. GROUP |
| | | | | | |
| | | BRIDGE FEE \$ | | CONST. TAX \$ | CONST. TYPE |
| | | | | | |
| | | WDF | 70.00 | TOTAL FEES \$ | OFFICE COPY REV. 9/79 |
| | | | | | |

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|---------|------------------------------|--------------------|---------------------|-------------------------------------|-----------------------------------|-------------|---|
| 1-11-82 | B \$192. | I-10097R \$20. | Const patio trellis | Morrison Homes | Kiku Landscape Inc. | Andy 3-1-82 | |
| 1-12-82 | P \$800.00 | I-10118R \$30.00 | Sprinkler System | Morrison Homes 4441 Auburn Blvd. | 3950 Happy Lane Kiku Landscape | 5/27/85 | NO FINAL INSPECTION CALLED BY PERMITEE. |
| 5/27/85 | | | | | | | |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|------------|---------------------|------------|---------------------|------------|---------------------|
| I-10097R | R 704F316 | I-10097R | R 704F316 | | |
| I-10097R | R 727F224 | | | | |
| I-10097R | R 704F316 | | | | |
| I-10097R | R 727F224 | | | | |
| I-10097R | R 704F316 | | | | |
| I-10097R | R 727F224 | | | | |
| I-10097R | R 704F316 | | | | |
| I-10097R | R 727F224 | | | | |
| I-10097R | R 704F316 | | | | |
| I-10097R | R 727F224 | | | | |
| I-10097R | R 704F316 | | | | |

I-1001

I-10097

I-10097R

REEL AND FRAME NOS.

PERMIT NO.

REEL AND FRAME NOS.

PERMIT NO.

REEL AND FRAME NOS.

PERMIT NO.

Check

Check

Check