

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------|--|------------------|-------|------|
| PERMIT NO. B-6416 | LOCATION 6283 - 2 nd Ave | | | |
| DATE 9/10/40 | PURPOSE New dwlg & garage | | | |
| ZONE 2-Fam | OWNER Martin Erickson | | | |
| | ARCH'T. H. N. Pierce | | | |
| | CON'T.R. H. N. Pierce | | | |
| VAL. 2500 ⁰⁰ | STORIES 1 | ROOMS 1 | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS | |
|----------|--|---------------------|
| 9/9-40 | 1 st | Lump Form on Pictor |
| 10/5-40 | 2 | " Frame " Pictor |
| 10/11/46 | 3 | " Lath 258 " Pictor |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div> | |