

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-476-</i>	LOCATION <i>5416- T.O.A.</i>			
DATE <i>5/2/38</i>	PURPOSE <i>Erect new dwlg.</i>			
ZONE <i>2-Fam</i>	OWNER <i>H. B. Brown</i>			
	ARCH'T.			
	CONT'R. <i>John Luddick.</i>			
VAL. <i>3400⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>980⁰¹</i>	
VENT SHAFTS		BOILER ROOMS	<i>@ 350</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS	
5/5-38	1 st	Ins p Forms ok Puts
5/23-38	2 nd	Ins p Frame " Puts
5/31-38	3	Ins p Frame + Puts

COMPLETE
AND O. K.

INSPECTOR