

BUILDING DIVISION BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V AT BUILDINGS

PERMIT NO. 4328 DATE	LOCATION 1 Blk V Highland Pl	2616-y PHONES			
	PURPOSE Store Bldg.				
1930 ZONE MAR 28 1929 SACRAMENTO BUILDING DIVISION	OWNER C. Maddison	ARCHT J. A. Saunders			
	CONTR J. A. Saunders				
	BUILDING DIVISION	STORIES 1	ROOMS 1	APTS. 1	SIZE 1

Steel Tested by	Held up for Re-examination	Elevator Shafts	
Cement Tested by		Holler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
Fire Escapes		Floor Tests	
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS
4/16/29	1 ST /NSP. Framing & Ceiling Floor ^{cond. O.K.} O.K. A.W. Campbell
5/17/29	2 ND /NSP. Frame. ^{106 Ventilation} Roof Trusses O.K. A.W. Campbell
5/21/29	3 RD /NSP INT. LATH O.K. A.W. Campbell R.H. Painter
6/4/29	4 TH /NSP. STORE B206 Completed A.W. Campbell
6/4/29	ISSUED CERTIFICATE OF OCCUPANCY # 4308
	Note. Scuttle to be cut in ceiling & roof. Also all surplus
	bdg. materials & debris to be moved from site and off property.
6/4/29	<p style="text-align: center;">COMPLETED AND O. K.</p> <p style="text-align: center;">A.W. Campbell R.H. Painter</p> <p style="text-align: right;">INSPECTOR</p>