

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS 5-21-11

PERMIT NO. <i>B-34094-</i>	LOCATION <i>5321-Whittier Drive</i>
DATE <i>Dec. 6-51</i>	PURPOSE <i>Erect new double garage</i>
ZONE	OWNER <i>Roune Rount &amp; Rount</i>
	ARCH'T.
	CONT'R. <i>Owner</i>

VAL. <i>5115<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	1023 <sup>A</sup> SIZE
-------------------------------	---------------------	-------------------	-------	------------------------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12-13-51	<i>frames</i> <i>R. Court</i>
1-16-51	<i>frames</i> <i>R. Court</i>
	COMPLETE AND O. K.

INSPECTOR