

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-411</i>	LOCATION <i>7317 - 140<sup>th</sup></i>
DATE <i>4/22/38</i>	PURPOSE <i>Alterations - repairs to restaurant</i>
ZONE <i>Gen Com.</i>	OWNER <i>L. M. Lockell</i>
	ARCH'T.
	CONTR.

VAL. <i>100<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

<b>DATE</b>	<b>CONDITION OF WORK—REMARKS</b>

**COMPLETE  
AND O. K.**

**INSPECTOR**

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-411</b>	LOCATION <b>2317 Y St</b>			
DATE <b>APR. 22. 38</b>	PURPOSE <b>Make Alterations &amp; Repair for Restaurant</b>			
ZONE <b>Gen. Com.</b>	OWNER <b>L. M. Lasell, same</b>			
	ARCH'T.			
	CONTR. <b>OWNER (day-work)</b>			
VAL. <b>100<sup>00</sup></b>	STORIES <b>1</b>	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE

CONDITION OF WORK-REMARKS

4/22/38

Made Partial Frame Inspections of some alterations for Restaurant. Provided vestibules + doors bet Restaurant room and 2 Toilets. Doing to enclose space in rear yard + screen in sand with window cut in rear room for kitchen with hooket opening bet. kitchen + bath. A.W. Campbell

COMPLETE  
AND O. K.

INSPECTOR