

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-73658</i>	LOCATION <i>1022-5th St.</i>			
DATE <i>4/12/45</i>	PURPOSE <i>Repairs to dwlg due to fire loss</i>			
ZONE	OWNER <i>J. Paz</i>			
	ARCH'T. <i>Dan Tatti</i>			
	CON'T.R. <i>Dan Tatti</i>			
VAL. <i>500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

11/11/11 11:11 AM

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="323 837 445 875">COMPLETE AND O. K.</p> <p data-bbox="1173 850 1303 871">INSPECTOR</p>