

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-5691</i>	LOCATION <i>308-V (H.)</i>
DATE <i>6/340</i>	PURPOSE <i>Repairs to dwlg.</i>
ZONE	OWNER <i>Martin Agatha</i>
	ARCHT.
	CONTR. <i>Walsh Roofing Co.</i>

VAL.	STORIES	ROOMS	APTS.	SIZE
<i>1900</i>				
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/5/40	1 <sup>ST</sup> / NSP. Frame for 15 ft beam to use 17 Md. double beam <sup>OK</sup> AW Complete
6/12/40	2 <sup>ND</sup> / NSP. Frame in place <sup>OK</sup> AW Complete Bring it up still in on table 7 Ad. beam <sup>OK</sup> AW Complete
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="315 1081 463 1122">COMPLETE AND O. K.</span> <span data-bbox="1312 1095 1463 1116">INSPECTOR</span> </div>