

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-7299</i>	LOCATION <i>577 - Robertson Way</i>
DATE <i>1/8/44</i>	PURPOSE <i>Erect new dwlg. gas</i>
ZONE	OWNER <i>W. P. Estes, J.</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>5500⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1183 @ 350</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
1/30/41	1 ST INSP. Forms in place ^{OK} Alden W. Campbell
3/17/41	2 ND INSP. Frame ^{OK} Alden W. Campbell
3/24/41	3 RD INSP. INT + EXT LATH ^{OK} Alden W. Campbell
5/30/41	4 TH INSP. Dry & Garage Completed ^{OK}
5/30/41	COMPLETE AND O. K. Alden W. Campbell

INSPECTOR