

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-12225</i>	LOCATION <i>1012 - 2nd Street -</i>
DATE <i>4/18/44</i>	PURPOSE <i>Alteration to interior Bldg.</i>
ZONE	OWNER <i>M. H. Leary</i>
	ARCHT.
	CONTR. <i>Owner</i>

VAL. <i>25000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE.	CONDITION OF WORK-REMARKS
5/3/24	Made inspection of interior of Hotel Rooms including Toilet Room on 2 nd & 3 rd Floors of Hotel Bldg. OK W Campbell
6/18/24	A TH WSP. Above work completed OK

6/18/24	
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. W Campbell INSPECTOR </div>

117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200