

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No Charge</i>	LOCATION <i>1071 1/2 A^{TR} ST.</i>			
DATE <i>2/6/36</i>	PURPOSE <i>Relate with 5/8" Plaster board and rec.</i>			
ZONE <i>General Commercial</i>	OWNER <i>F. Paroi</i>			
	ARCH'T. <i>Plaster Ceiling of 2nd Story</i>			
	CONT'R. <i>OWNER 330 K ST.</i>			
VAL. <i>7500</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
2/6/36	3 rd Insp. Owner used Rock Lath over old wood lath on Ceiling of 2 nd Story where all old plaster was removed - Fire Zone. O.K. Ed Campbell

COMPLETE
AND O. K.

INSPECTOR