



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
5819 Bamford Drive		5819 Bamford Drive		5-C	
LEGAL DESCRIPTION					
Larchmont Valley HJ Unit No 10 Lot 726					
TITLE AND NAME					
1/c					
GEN. CONTR.					
Owner					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
M.H. Stonham					
OWNER					
M.J. Brock & Sons					
CONST. LOAN LENDER					
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
NO. OF STORIES		ROOF CONSTR.		AREA 1st FLOOR	
1		compo			
SIDE YARDS		REAR YARDS		SET BACK REQ.	
USE ZONE		PARK'G. REQ.		SPACES	
1					
TREES RMWD.		EXISTING BLDG'S SAME LOT		HOW USED	
TOTAL AREA		C.S.D.		C.I. CASE	
95821		1127			
CENSUS TRCT. NO.		EXISTING BLDG'S SAME LOT		HOW USED	
1127					
NATURE OF WORK:- Const Dwelling with at gar MP #127 RDP 5173 street width 54					

PERMIT NO. S.P.	F1289	ISSUED BY	JK
ISSUANCE DATE	2-22-78	PLANS AND APPLICATION	REEL NO. 5138119
VALUATION	\$ 22,930.00	INSPECTION RECORD	REEL NO. 5138119
R.O.F. FEE	\$ 191.00	JOB FILE	REEL NO. 5138119
S.M.L. FEE	\$ 1.61	FRAME NO. TO	53228175
PLAN CHECK FEE	\$	FRAME NO. TO	53228175
SEWER INCL. FEE	\$	REMARKS AND/OR VARIANCES	
PERMIT FEE	\$ 218.00		
TOTAL FEES	\$ 410.61		

INSPECTION AREA	
FINAL INSPECTIONS	
DATE	
BUILDING BY	
DATE	
ELECTRICAL BY	
DATE	
PLUMBING BY	
DATE	
MECHANICAL BY	
DATE	
CERTIFICATE OF OCCUPANCY	
ISSUED BY	
DATE	