

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

PERMIT No. <i>A-2020</i>	LOCATION <i>3008-V Street</i>
DATE <i>9/18/34</i>	PURPOSE <i>Joining Firemen's Assoc.</i>
ZONE <i>Gen. Com.</i>	OWNER <i>Mrs Hughes</i>
	ARCH'T <i>A - Larson</i>
	CONT'R <i>A - Larson</i>

VAL. <i>17500</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
9/19/34 9/25/34	<del>1<sup>st</sup> NSP</del> 1 <sup>st</sup> NSP Exc. 1 <sup>st</sup> NSP Forms for Enlarged Basement Walls <sup>O.K.</sup> M. Campbell
10/17/34	1 <sup>st</sup> NSP " " 3" Concrete Floor Step Walls M. Campbell
11/9/34	Made Inspection at request of Owner as Basement leaked after recent storm, along intersection at floor and at joint between old & new concrete Basement Wall. A few days later Contractor cut V-groove at intersection of wall & floor and treated joint between old & new work with Mastic Compound & Cement grout.
2/28/35	Appeared as Witness of Hearing of State Contb. License Board as to work done. M. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>