

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|---------|------------------------------|--------------------|----------------------------|------------------------------|--------------------------------------|------------------|----------------|
| 7-19-79 | PE \$1663.00 | G-6771 \$55. | General repairs as per HUD | HUD XXXXXXXX | Hamburg Const 5518 Date Ave 95842 | <i>W. L. ...</i> | <i>8/28/79</i> |
| 5/14/82 | B \$864. | J-974R \$30. | Install covered patio | Mary James 2 Pavilion Ct. | Owner | <i>W. L. ...</i> | <i>8/28/79</i> |
| | | | | | | <i>NASCA</i> | <i>8.26.82</i> |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|------------|---------------------|------------|---------------------|------------|---------------------|
| G-6771 | R 581 F 074 | | | | |
| G-6771 | R 589 F 566 | | | | |
| J-974R | R 723 F 445 | | | | |
| J-974R | R 743 F 100 | | | | |