

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A7706</i>	LOCATION <i>907 - 6th Street</i>			
DATE <i>1/13/38</i>	PURPOSE <i>Reconstruct cur. sidewalk</i>			
ZONE <i>Gen. Com.</i>	OWNER <i>Friedrich Mies Co</i>			
	ARCHT. <i>J. C. Doye Civil Engineer, ^{Representative} General</i>			
	CONTR. <i>Carl Fiedler</i>			
VAL. <i>500⁰⁰</i>	STORIES	ROOMS	APPS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/10/38	Made Partial Drop of Remaining Condemned sidewalk built on timbers - Contractor has not removed same preparatory to constructing Re Def. Conc. sidewalk with Steel I Beams & Re Def. Conclat sidewalk
1/24/38	2 nd Insp. Steel I-Beams & Re Def. Conc. in place also forms in place O.K. A.W. Campbell
1/28/38	4 th Insp. Sidewalks Completed and opened to traffic O.K.
1/28/38	COMPLETE AND O. K. <i>A.W. Campbell</i> INSPECTOR