

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS	
		4820 Alturas Way						BUILDING BY	
LEGAL DESCRIPTION		OCCUP. GR.	CONST TYPE	*VAR. NO.	FIRE ZONE	DATE			
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	
GEN. CONTR.								DATE	
ELEC. CONTR.								PLUMBING BY	
PLBG. CONTR.								DATE	
MECH. CONTR.								MECHANICAL BY	
ARCH. ENGR.								DATE	
OWNER								CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
							CENSUS TRCT. NO.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:-

PERMIT NO. S.P. -	MICROFILM RECORD			
ISSUED BY				
ISSUANCE DATE				
VALUATION \$	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$	REMARKS AND/OR VARIANCES			
\$				
\$				
TOTAL FEES \$				

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
8-18-71	bldg \$12,400.	H-2880 \$57.	const family rm, bed rm, & den on rear of dwelling	Bill Bailey same	R.A. Collin 3551 N Street	Riolo	2-8-73
11-26-63	bldg \$200.00	E5660 \$5.	repair termite damage to dwelling	William Ridgeway same	Valley Termite	Barbato	12-2-63
2/2/76	P.E. \$6,800.	D-625 \$60.	Swimming Pool - Dwlg.	William C. Bayley Same <i>1-3172</i>	Capitol Pools Inc. 4739 Auburn Ave	<i>Rae Jacobs</i>	<i>6-30-76</i> <i>11/16/76P</i>

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
H-2880	R309 F364-366				
E-5660	R133 F104				
H-2880	R407 F134 - 37				
D-625	R435 F136-137				
D-625	R477 F081 <i>final</i>				