

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD F 319

## TYPE BUILDINGS \$3.00

PERMIT NO. G-6937	LOCATION 2322 <sup>1</sup> / <sub>2</sub> -6th St.			
DATE July 18, 57	PURPOSE Repair rear porch and Kitchen			I-V
ZONE	OWNER Jose R. Torres			
	ARCH'T			
	CONT'R Owner		GL 34112	
VAL. \$250/	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	INSPECTOR		
FORM		/		
JOIST				
FRAME				
LATH				
FINAL	2-5-58			

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
	<p data-bbox="291 853 408 899"><b>COMPLETE AND OK</b></p> <p data-bbox="1111 878 1234 902"><b>INSPECTOR</b></p>