

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPES I, II, III, IV, V, VI BUILDINGS**

<b>PERMIT NO.</b>  7189	<b>LOCATION</b>  2570 Franklin Blvd	<b>PHONES</b>
<b>DATE</b>  10/17/20	<b>PURPOSE</b>  1. Sign	
<b>ZONE</b>  Linn Ret	<b>OWNER</b>  Bayless Bond	
	<b>ARCH'T</b>  [Signature]	
	<b>CONT'R</b>  [Signature]	

<b>VAL.</b>  201	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
------------------------	----------------	--------------	--------------	-------------

<b>Steel Tested by</b>		<b>Elevator Shafts</b>	
<b>Cement Tested by</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector Rfd. Conc.</b>		<b>Sprinkler System</b>	
		<b>Floor Tests</b>	
<b>Fire Escapes</b>			
<b>Stand Pipes</b>			

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="302 840 450 885">COMPLETED AND O.K.</p> <p data-bbox="1059 865 1196 885">INSPECTOR</p>