

*R319F345*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$6.00

**TYPE BUILDINGS**

PERMIT NO. <b>H-5092</b>	LOCATION <b>1017 - V Street</b> <b>A-2 (9)</b>				
DATE <b>Jan. 7-72</b>	PURPOSE <b>Repair front porch of dwelling</b>				
ZONE <b>R-1</b>	OWNER <b>Leo Richter</b> <b>Same</b>				
	ARCH'T				
	CONT'R <b>W. Phillips 4968-San Marque Circle</b>				
VAL. <b>\$500.</b>	STORIES <b>1</b>	ROOMS	APTS.	/Carm.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) <b>487 3455</b>	
FORM	<i>1-13-72 Coast</i>				
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>4/14/76 [Signature]</i>				

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
	<b>COMPLETE AND OK</b>
	<b>INSPECTOR</b>