

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-32554</i>	LOCATION <i>241 - San Antonio Way</i>
DATE <i>Apr. 24 1957</i>	PURPOSE <i>Add room & Bath</i>
ZONE	OWNER <i>W. M. Smith</i>
	ARCH'T.
	CONTR. <i>E. J. Sheehy</i>

VAL. <i>1500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
4/30/51	Form Insp. O. E. Buckius
7/5/51	Frame " (Closest to Large) "
	<div data-bbox="302 828 446 875" data-label="Text">COMPLETE AND O. K.</div> <div data-bbox="1171 844 1323 875" data-label="Text">INSPECTOR</div>