

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

PERMIT NO. <i>NO. 24261</i> (REPAIRS) DATE <i>Oct 31</i> <i>1937</i>	LOCATION <p align="right" style="font-size: 1.5em;"><i>2716 O. ST.</i></p> PURPOSE <i>Rebuild Front Steps</i>
ZONE <i>Multiple Family</i>	PHONES OWNER <i>NEDIFFER &amp; WALTERS (AGENTS)</i>
CONT-R <i>OWNER</i>	ARCH'T

VAL.	<i>2500</i>	STORIES	ROOMS	APTS.	SIZE
------	-------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
10/31/32	Gave tenant No Charge Request to give
	to Owner for rebuilding front steps
	rotted out. A W Campbell
	COMPLETE AND O. K. INSPECTOR