

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-4772</i>	LOCATION <i>116 - 14<sup>th</sup> Street.</i>			
DATE <i>1/31/38</i>	PURPOSE <i>Repair stone bldg. fire damage</i>			
ZONE	OWNER <i>Capital Bldg. - Hoan Co.</i>			
	ARCH'T.			
	CONTR. <i>Chas Vanina</i>			
VAL. <i>2500<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
2/10/38	2 <sup>ND</sup> Insp. Frame for Roberts Fire Damage O.K. A.W. Campbell
2/10/38	3 <sup>RD</sup> Insp. (Part) South Section of Ceiling 3/8" Plaster bound over old lath used longer nails. O.K. A.W. Campbell
2/14/38	3 <sup>RD</sup> Insp. Reb. of INT. LATH <sup>ON</sup> A.W. Campbell

COMPLETE  
AND O. K.

INSPECTOR