

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>7001</i>	LOCATION <i>3601 - 7th Ave</i>		
DATE <i>Apr 2/20</i>	PURPOSE <i>Remod</i>	ROOMS	APTS.
ZONE <i>4</i>	OWNER <i>Miss M. Penczek</i>		PHONE
	ARCH'T		
	CONT'R <i>Blum R. & Co.</i>		
	VAL. <i>112.50</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			Cement Tests
Ex Wall	Joints						Chimneys		
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
9-24-30	Roof Composition now Completed

COMPLETED
AND O.K.

P. H. Hunter

INSPECTOR