

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-12988</i>	LOCATION <i>1121 - Terminal</i>			
DATE <i>12/5/44</i>	PURPOSE <i>Roof repairs</i>			
ZONE	OWNER <i>Sacramento Northern Ry.</i>			
	ARCH'T.			
	CONTR. <i>Hancey Co.</i>			
VAL. <i>18600</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="293 837 422 875">COMPLETE AND O. K.</p> <p data-bbox="1124 850 1253 875">INSPECTOR</p>