

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------------|--|------------------|-------|------|
| PERMIT NO. <i>B-2475</i> | LOCATION <i>1016 - 31st Street</i> | | | |
| DATE <i>2/17/39</i> | PURPOSE <i>Replace with Brick Wall</i> | | | |
| ZONE | OWNER <i>M. Protch</i> | | | |
| | ARCH'T. | | | |
| | CONTR. <i>Owner</i> | | | |
| VAL. <i>1850⁰⁰</i> | STORIES <i>1</i> | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|--|
| 2/25/39 | 1 ST /NSP. 2 Brick Piers for Rear Porch ^{OK} Rd Co. work |
| 2/25/39 | 2 ND /NSP. Frame for new 12' Brick Wall on Right side and 2 - 6'x6' Posts to support it |
| | New Porch Wall. ^{OK} R N Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p> |