

R222 F398

389	BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD		\$49.00
Southgate Meadows #6		TYPE BUILDINGS	R 216 F542-549
PERMIT NO.	LOCATION		
F-8182	7711 Guinby Way		A-5
DATE	PURPOSE	102-S	
Aug. 14/67	Const. dwelling & garage		
ZONE	OWNER	2777-Alvarado St.	
R-1	ARCH'T	/383-9315	
	CONTR	Besco 2777 Alvarado St., San Leandro	
VAL	\$13,600.	STORIES	ROOMS
		1	5
			APTS.
			476 gar. SIZE
			1,377 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP
FORM	9-6-67	Larsen	
JOIST	9-20-67	Larsen	
FRAME	10-17-67	Larsen	
SHEET ROCK	10-25-67	Larsen	
FINAL	1-9-68		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
9-5-67	Pt Room - not ready Larson
9-19-67	Pt Juit - wood & debris. Double
	juit. Remove your Larson
COMPLETE AND OK	INSPECTOR