

*B121 9329-334*

Lt. 26 **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$64.00

Meadowview Gardens **TYPE BUILDINGS**

PERMIT NO. E-3853	LOCATION 1900-O'Neal Way & 7415-19th Street	A-5		
DATE May 9-63	PURPOSE Const. Duplex & attached garages			
ZONE R-2	OWNER Robert Buckman 3801-64th Street			
	ARCH'T			
	CONTR Owner	Same	GL 5-3330	
VAL. \$18,600.	STORIES 1	ROOMS 7	APTS. 2	SIZE 1,900 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	
FORM	<i>5-27-63</i>	<i>Hammond</i>		
JOIST	<i>6-11-63</i>	<i>Hammond</i>		
FRAME	<i>7-24-63</i>	<i>Hammond</i>		
SHEET ROCK	<i>8-2-63</i>	<i>Fulley</i>		
FINAL	<i>8-3-63</i>	<i>C. Hammond</i>		

*H*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
6-6-63	PT 4 on plumbing map. All tubes not backfilled Hammer
6-7-63	PT Piers under fireplace garden Court
6-10-63	PT 4 on straps on 4x6 piers where kid into 4x6 string Hammer
7-22-63	PT 4 numerous items Hammer
7-31-63	PT SB not nailed. No address Hammer
11-22-63	PT 4 on base number 2nd & 3rd PT fireplace damper did not open. 1st floor
11-27-63	duct must be 1" from wall Hammer
12-2-63	COMPLETE PT fireplace damper incorrect AND OK

INSPECTOR  
12/2/63