

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2638</i>	LOCATION <i>1531 - U St.</i>
DATE <i>2/15/39</i>	PURPOSE <i>Repairs to restaurant</i>
ZONE <i>-</i>	OWNER <i>Henry Weiss</i>
	ARCH'T. <i>Chas Vesina</i>
	CONTR. <i>Chas Vesina</i>

VAL *500*

STORIES

ROOMS

APTS.

SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE

CONDITION OF WORK-REMARKS

3/1/39

2nd / NSP. Frame for replacing wood girders
& center posts with New Steel I Beams
Girders with Steel Posts at either end
to eliminate posts in Cape.

O. K. A. W. Campbell

COMPLETE
AND O. K.

INSPECTOR