

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>M chg</i>	LOCATION <i>2721-5 St</i>	
	PURPOSE <i>Reroof Composition</i>	ROOMS / APTS.
DATE <i>2/23-30</i>	OWNER <i>Frank M. Fuller</i>	PHONE
ZONE	ARCH'T	
	CONT'R	
	VAL. <i>6000</i>	STORIES   SIZE

FOUNDATION	STORY	BSMT.	1	2	3	ROOF		
Ex Wall	Jolts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="331 870 495 916"><b>COMPLETED AND O.K.</b></p> <p data-bbox="1182 890 1332 916"><b>INSPECTOR</b></p>