

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5676</i>	LOCATION <i>3925 - 5 St.</i>			
DATE <i>5/29/40</i>	PURPOSE <i>Repairs to Roof Add Torch</i>			
ZONE <i>L</i>	OWNER <i>Sydney Ingalls</i>			
	ARCH'T. <i>Owner</i>			
	CONT'R. <i>Owner</i>			
VAL. <i>28000</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="308 884 446 926">COMPLETE AND O. K.</p> <p data-bbox="1203 899 1344 919">INSPECTOR</p>